

3B ^{IDEM} DEPTM. OF ENVIRONMENTAL MANAGEMENT
cwk

INDIANAPOLIS

OFFICE MEMORANDUM

DATE: November 23, 1987

THRU: Harry Atkinson

MAH 11/30

TO: File Wayne County G.3
Richmond sitesFROM: Mary Anne Hunter
Site Investigation Section

MAH 11/24/87

EPA Region 5 Records Ctr.



348890

SUBJECT: Windshield Surveys

On 11/13/87, I accompanied Bob Gowens of the Wayne County Health Department on site surveys.

Springwood Lake. A visit to the park and conversations with the county health department indicate no dump in the park. The park was created in the 1930's. It is a springfed lake. Surface water (via Brown ditch) drainage has been used over the years to bring the water level up. Brown ditch was inspected at several points upstream of the lake. There was no indication of stressed vegetation or build-up of wastes. Near the valve by the walk bridge north of the lake, there was a pale milky appearance of the water. No odor other than iron, algae and sulphur was discernible.

Sanyo. North of Sanyo along the hill edge (east) there are piles of black materials. This is also the area of the old AVCO (Crosley) dump area. There is allegedly a discharge to the ditch.

Dana. Large areas of foundry sand wastes up to 40 feet high exist east of the main plant building. For at least 30 minutes Dana appeared to have a 100% opacity rating from its main stack.

Alcoa. No disposal areas are visible from the road.

Duetz. No visible disposal areas.

The condition of Springwood Lake is deteriorated. Vegetation is growing in the lake. At one time, part of the lake was thought to be 30 feet deep. Much of the depth appears to be silted in. Ducks and geese are resident. The sand in the beach area appears normal. No abnormal discoloration is evident in sediment or water. At least one discharge pipe is visible on the SW side of the lake. Brown ditch is continuously flowing due to plant discharges.

Belden. No disposal areas are visible from the road.

MAH/cl's

To Richmond

STATE ROUTE No. 627

WILLIAMSBURG Pkwy

PENNSYLVANIA SPRING

STORM SEWER + 3128

DESIGN AND MANUFACTURING

FRESH WATER HEADER

STORM SEWER

FRESH WATER HEADER

STORM SEWER + 3128

GRASS FIELD

48" STORM SEWER OUTLET

CAREX

STORAGE TRACK

STORM SEWER OUTLET

36"

RAILROAD

TOP OF RAVINE

OHIO

CHESAPEAKE

AND

17

18

19

20

21

22

23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

40

41

42

43

44

45

46

47

48

17

18

19

20

21

22

23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

40

41

42

43

44

45

46

47

48

49

50

51

52

53

54

55

56

57

58

17

18

19

20

21

22

23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

40

41

42

43

44

45

46

47

48

49

50

51

52

53

54

55

56

57

58

20

21

22

23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

40

41

42

43

44

45

46

47

48

49

50

51

52

53

54

55

56

57

58

59

60

22

23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

40

41

42

43

44

45

46

47

48

49

50

51

52

53

54

55

56

57

58

59

60

22

23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

40

41

42

43

44

45

46

47

48

49

50

51

52

53

54

55

56

57

58

59

60

23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

40

41

42

43

44

45

46

47

48

49

50

51

52

53

54

55

56

57

58

59

60

Water Pollution Control Division

~~GFA~~
~~MAS~~
File

INSPECTION SECTION
INSPECTION REPORT FORM

Name of Company DESIGN & MANUFACTURING CO. Date 3/15/84
City RICHMOND 47374 County WAYNE Telephone No. 317/962-4511
Persons Contacted PAUL FULLER - LAB TECH & ENVIRONMENTAL CONTROL
Purpose of Inspection MINOR OVERVIEW
Products DISHWASHERS & REFRIGERATORS
No. of Employees 1000 Receiving Stream EAST FORK OF WHITEWATER RIVER
Source of Water CITY No. of Outfalls 2
Sewage Disposal CITY Waste flow 001: 0.293MGD 002: 0.07MGD
Permit No. IN 0049972 Certified Operator P. FULLER - CLASS D
Status: Adequate Inadequate Undetermined-Submitted
By G. M. CLURE.

Description of production, manufacturing operations, waste treatment facilities,
liquid waste disposal, cooling water additives, boiler treatments, permit compliance.
General remarks, comments, recommendations, conclusions.

Both outfalls consist of non-contact cooling
and storm water run-off. These outfalls serve
both Design & Manufacturing and its subsidiary
ABSOCOLD.

Both discharges looked very clear at this
time, as did the areas adjacent to the discharge
pipe.

MAIL MONEY RECEIPT

DATE **12/18/81** RECEIPT NO. **J 93623**

DIVISION

WP

FROM

Design and Mfg. Corp.

STREET

3333 Sheridan Avenue

CITY

STATE

RR Richmond, IN 47374

<input type="checkbox"/>	VITAL RECORDS
<input type="checkbox"/>	WASTEWATER
<input type="checkbox"/>	MOBILE HOME PARK
<input type="checkbox"/>	PRIVATE WATER
<input type="checkbox"/>	MOTEL
<input type="checkbox"/>	PUBLIC WATER
<input type="checkbox"/>	NURSING HOME
<input type="checkbox"/>	BEDDING
<input type="checkbox"/>	DAIRY PERMIT
<input type="checkbox"/>	PREMARITAL
<input type="checkbox"/>	FROZEN FOOD
<input type="checkbox"/>	SEPTIC TANK
<input type="checkbox"/>	HEARING AID
<input checked="" type="checkbox"/>	OTHER

REMARKS

S833 7 1A 1150.00 PR
S833 1150.00 TL
S833 1A 1150.00CKT
S833 12/18/81
S834 7 VDI A 1150.00 PR
S834 1A 1150.00CKT
S634 12/18/81
S835 7 1A 150.00 PR
S835 150.00 TL
S835 1A 150.00CKT
S835 12/18/81

NPDES

AMOUNT

\$150.00

BUSINESS CHECK

23148

MONEY ORDER #

CASH

MAIL CLERK

ad

DISPOSITION:
DATE DEPOSITED

CERTIFIED CHECK

PERSONAL CHECK

STAMPS

OTHER

RECEIVED ACCOUNTING DIVISION

DATE RETURNED